

ERRATA SHEET FOR ASHRAE GUIDELINE 16-2018
Selecting Outdoor, Return, and Relief Dampers
for Air-Side Economizer Systems

July 27, 2018

The corrections listed in this errata sheet apply to all copies of ASHRAE Guideline 16-2018. The first printing is identified as “Product code: 86849 4/18” on the outside back cover.

<u>Page</u>	<u>Erratum</u>
--------------------	-----------------------

- | | |
|----------|---|
| 8 | 4.4.3.2 In Section 4.4.3.2 change the reference to Section “4.3.3.2” to “4.3.3.3” as shown below.
<i>(Note: Additions are shown in <u>underline</u> and deletions are shown in strikethrough.)</i> |
| | 4.4.3.2 Select the economizer outdoor-air damper (D-3) as instructed in Section <u>4.3.3.3</u> 4.3.3.2 . |