

**ERRATA SHEET FOR
ANSI/ASHRAE STANDARD 33-2000
Method of Testing Forced Circulation Air Cooling and Air Heating Coils**

February 2, 2016

The corrections listed in this errata sheet apply to all copies of ASHRAE Standard 33-2000.

Page Erratum

- | | |
|-----------|--|
| 3 | 5.2.4. In Section 5.2.4 change “∞” to “x” (multiplication symbol) in both the I-P and SI equations. |
| 15 | 11.9.1. In the second equation in Section 11.9.1 change “?” to “≥” in two places. |
| 15 | 11.9.2. In the second equation in Section 11.9.2 change “?” to “≥” in two places. |