Errata to Advanced Energy Design Guide for Grocery Stores— Achieving 50% Energy Savings Toward a Net Zero Energy Building (2015)

April 29, 2015

Pages 71, 75, 79, 83, 87, 91, 95, 99:

In the Daylighting/Lighting > Interior Lighting section of each of the climate zone recommendation tables in Chapter 4, the how-to tip listed for the entry "All CFL and HID ballasts" reads "EL13," but the EL how-to tips were misnumbered in the first printing. For convenience, change all the "EL13" listing in the Chapter 4 recommendation tables to "EL12."

Page 128:

The figure caption needs to include "(**DL8**)" at the beginning of it, and the (a) and (b) for the figures need adjusting. Please refer to the following corrected figure:




Figure 5-13 (DL8) Daylighting Ceiling Configurations: (a) Raised Ceiling at Façade and (b) Sloped Ceiling at Façade

Page 162: Kitchen Equipment how-to tip KE7 should be numbered "KE6."

