

ERRATA SHEET FOR ASHRAE GUIDELINE 12-2020
Managing the Risk of Legionellosis Associated with Building Water Systems

May 15, 2020

The corrections listed in this errata sheet apply to ASHRAE Guideline 12-2020. The first printing is identified on the outside back cover as “Product code: 86865 4/20”.

Page Erratum

- 39 9.1.5.1 Portable Impeller Humidifiers.**
(Note: Additions are shown in underline.)
- 9.1.5.1 Portable Impeller Humidifiers.** Portable impeller humidifiers (Figure 6) produce [...]
- 40 Figure 6 Portable impeller humidifier.** Add Figure 6 as shown in the attached.
- 40 10. Indirect Evaporative Air Coolers.** Revise Section 10, second paragraph, as shown below.
(Note: Deletions are shown in ~~striketrough~~.)
- Indirect evaporative cooling (IEC) provides a cool airstream through the use of a heat exchanger that is cooled by the evaporation of water. IEC evaporatively cools one side of a heat exchanger, which transfers heat to the primary airstream as shown in Figures ~~6 and 7~~. [...]
- 41 Figure 7 Indirect evaporative air coolers.** Add Figure 7 as shown in the attached.




Figure 6 Portable impeller humidifier.





Figure 7 Indirect evaporative air coolers.